

# Safety Data Sheet

## H3410 PERFECT CAST DEEP HARDENER



### Section 1: Identification of the Material and the Supplier

Trade Name	H3410 PERFECT CAST DEEP HARDENER
Product Code	H3410
Recommended Use	Used in conjunction with epoxy resin for adhesive and composites applications
Company	ATL Composites
Address	12-14 Production Ave Ernest 4214
Telephone	+61 7 5563 1222 (Monday-Friday 8:30am-5:00pm)
Emergency Telephone Number	+61 7 5563 1222 (Monday-Friday 8:30am-5:00pm)
Revision Date	22 <sup>nd</sup> November 2018

### Section 2: Hazards Identification

GHS Classification:	Skin corrosion (Category 1) Serious eye damage (Category 1) Acute toxicity, oral (Category 4) Acute toxicity, dermal (Category 4) Acute toxicity, inhalation (Category 4) Acute aquatic toxicity (Category 2) Chronic aquatic toxicity (Category 2)
---------------------	---

#### GHS Label elements, including precautionary statements

Pictogram



Signal word      Danger

Hazard statement(s)

H302	Harmful if swallowed
H312	Harmful in contact with skin
H314	Causes severe burns and eye damage.
H317	May cause allergic skin irritation.
H332	May be harmful if inhaled.
H411	Toxic to aquatic life with long lasting effects.

Precautionary statement(s)

P261	Avoid breathing dust / fumes / gas / mist / vapours / spray/
------	--

# Safety Data Sheet

## H3410 PERFECT CAST DEEP HARDENER



P270 Do not eat, drink or smoke when using this product.  
P280 Wear protective gloves / eye protection / face protection.

Response

P302 + P361 + P353 IF ON SKIN (or hair): Remove / take off immediately all contaminative clothing. Rinse skin with water / shower.  
P301 + P330 + P331 IF SWALLOWED: rinse mouth. Do NOT induce vomiting.  
P305 + P351 + P338 IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.

P310 Immediately call a POISON CENTER or doctor / physician.  
P333 + P313 If skin irritation or rash occurs: Get medical advice / attention.  
P363 Wash contaminated clothing before reuse.

Disposal

P501 Dispose of contents / container to an approved waste disposal plant

### Section 3: Composition / Information on Ingredients

Chemical Name	CAS No.	Weight %
2,2'-Dimethyl-4,4'methylenebis(cyclohexylamine)	6864-37-5	<10
Trimethylolpropane tris[poly(propylene glycol), amine terminated] ether	39423-51-3	>60
Polyamine blend	-	<10
Other ingredients determined not to be hazardous	-	To 100

### Section 4: First Aid Measures

General Advice Seek medical advice. If breathing has stopped or is laboured give assisted respirations. Supplemental oxygen may be indicated. If the heart has stopped begin cardiopulmonary resuscitation immediately.

Inhalation Remove the source of contamination or move the victim to fresh air. Ensure airways are clear and have qualified person give oxygen through a face mask if breathing is difficult. If symptoms develop and persist seek medical attention.

Ingestion DO NOT INDUCE VOMITING. Immediately wash out mouth with water. If symptoms persist seek medical attention.

Skin Wash affected area thoroughly with soap and water. Remove contaminated clothing and wash before reuse or discard. If symptoms develop seek medical attention.

Eye If contact with the eye(s) occurs, wash with copious amounts of water holding eyelid(s) open. Take care not to rinse contaminated water unto

# Safety Data Sheet

## H3410 PERFECT CAST DEEP HARDENER



ATL composites

---

	the non-affected eye. If symptoms persist seek medical attention.
First Aid Facilities	Eye wash and normal wash room facilities.
Advice to Doctor	Treat symptomatically
Other Information	For advice, contact a Poisons Information Center (Phone e.g Australia 131 126)

---

### Section 5: Fire Fighting Measures

Suitable extinguishing media	Use water spray, carbon dioxide, dry chemical or foam.
Hazards from Combustion Products	Under fire conditions this product may emit toxic and/or irritating fumes including Oxides of Carbon and Oxides of Nitrogen.
Precautions in connection with Fire	Full protective clothing and self-contained breathing apparatus. Operated in a positive pressure mode. Water spray may be used to keep fire exposed containers cool.

---

### Section 6: Accidental Release Measures

Emergency procedures	Wear appropriate personal protective equipment and clothing to minimise exposure. Extinguish or remove all sources of ignition and stop leak if safe to do so. Increase ventilation. Evacuate all unnecessary personnel. If possible contain the spill. Place inert absorbent material onto spillage. Use clean non-sparkling tools to collect the material and place in a suitable labelled container. Do not dilute material but contain. Dispose of waste according to federal, Environmental Protection Authority and state regulations. If the spillage enters the waterways contact the Environmental Protection Authority, or your local Waste Management Authority.
----------------------	---

---

### Section 7: Handling and Storage

#### Storage

Precautions for Safe Handling	Do not get into eyes, on skin or on clothing. Use only with adequate ventilation. Avoid contact with skin, eyes and clothing. Avoid prolonged or repeated contact with skin, eyes and clothing. Wash thoroughly after handling. DANGER. Corrosive to the eyes, corrosive to the skin. Maybe harmful if swallowed. Causes respiratory tract irritation. May cause skin sensitisation. Containers, even those that have been emptied, can contain hazardous product residues. Wash with soap and water before eating, drinking, smoking, applying cosmetics, or using toilet facilities. Launder contaminated clothing before reuse. Contaminated leather articles, including shoes cannot be decontaminated and should be destroyed to prevent reuse.
Conditions for Safe Storage	Store under inert gas. Moisture sensitive. Sensitive to Carbon Dioxide. Keep container tightly closed in a dry and well ventilated place out of

# Safety Data Sheet

## H3410 PERFECT CAST DEEP HARDENER



direct sunlight. Keep containers closed when not in use.

---

### Section 8: Exposure Controls / Personal Protection

National Exposure Standards	No exposure standards have been established for this material by the Australian National Occupational Health and Safety Commission (NOHSC) or the Occupational Safety and Health Service (OHS) of the New Zealand Department of Labour. However, exposure standards for ingredients are stated below: Australian National Occupational Health and Safety Commission (NOHSC) exposure standards:
Biological Limit Values	No biological limit allocated.
Engineering Controls	Provide sufficient ventilation to keep airborne levels below the exposure limit. Where vapours or mist are generated, particularly in enclosed areas, and natural ventilation is inadequate, a local exhaust ventilation system is required. Provide readily accessible eye wash stations and safety showers.
Respiratory Protection	Where ventilation is inadequate the use of an Air Purifying Respirator with a replaceable organic vapour filter complying with AS/NZS 1715 and AS/NZS 1716 is recommended.
Eye Protection	Safety glasses with side shields, goggles or full-face shield as appropriate recommended. Final choice of appropriate eye/face protection will vary according to individual circumstances i.e. methods of handling or engineering controls and according to risk assessments undertaken. Eye protection should conform with Australian/New Zealand Standard AS/NZS 1337 – Eye protectors for Industrial Applications.
Hand Protection	Wear gloves of impervious material such as impervious PVC or rubber gloves. Final choice of appropriate gloves will vary according to individual circumstances i.e. methods of handling or according to risk assessments undertaken. Reference should be made to AS/NZS 2161.1 Occupational protection gloves – Selection use and maintenance.
Body Protection	Suitable work wear should be worn to protect personal clothing. Industrial clothing should conform to the specifications detailed in AS/NZS 2919: Industrial Clothing.

---

### Section 9: Physical and Chemical Properties

Form	Low Viscosity Liquid
Colour	Clear
Odour	Amine like
pH	Not Available
Melting Point	Not Available
Flash Point	113°C (Closed Cup)

# Safety Data Sheet

## H3410 PERFECT CAST DEEP HARDENER



ATL composites

Boiling Point	>247°C
Vapour Density	Not Available
Vapour Pressure	0.0157 hPa @ 20°C (OECD Test Guideline 104)
Density	0.95 to 1.00
Auto-Ignition Temperature	Not Available
Flammable Limits – Lower	Not Available
Flammable Limits – Upper	Not Available

---

### Section 10: Stability and Reactivity

Chemical Stability	Stable under normal conditions.
Conditions to Avoid	Extremes of temperature and direct sunlight. Exposure to water vapour.
Incompatible Materials	Strong oxidising agents.
Hazardous Decomposition Products	Nitrogen oxides Carbon Monoxide Carbon Dioxide

---

### Section 11: Toxicological Information

Acute oral toxicity	2,2'-Dimethyl-4,4'methylenebis(cyclohexylamine) Oral >3000 mg/kg ATE <sub>mix</sub> Trimethylolpropane tris[poly(propylene glycol), amine terminated] ether 600mg/kg
Acute dermal Toxicity	2,2'-Dimethyl-4,4'methylenebis(cyclohexylamine) Dermal >2000 mg/kg ATE <sub>mix</sub>
Inhalation	2,2'-Dimethyl-4,4'methylenebis(cyclohexylamine) Vapours 4.31mg/L ATE <sub>mix</sub>
Ingestion	If ingested, severe burns of the mouth and throat.
Skin	2,2'-Dimethyl-4,4'methylenebis(cyclohexylamine) Skin Rabbit Result – causes severe burns
Eyes	2,2'-Dimethyl-4,4'methylenebis(cyclohexylamine) Rabbit

# Safety Data Sheet

## H3410 PERFECT CAST DEEP HARDENER



ATL composites

Result – Corrosive to eyes – 24 h  
(OECD Test Guideline 405)

Chronic Effects Prolonged or repeated contact may result in irritation and/or allergic contact dermatitis.

### Chronic toxicity or effects from long term exposures

Carcinogenicity No component of this product present at levels greater than or equal to 0.1% is identified as probable, possible or confirmed human carcinogen by IARC.

Reproductive toxicity No data available

Germ cell mutagenicity Assessment of mutagenicity: No mutagenic effect was found in various tests with bacteria and mammalian cell culture. The substance was not mutagenic in a test with mammals.

Specific target organ systemic toxicity (single exposure) No data available

Specific target organ systemic toxicity (repeated exposure) No data available

Aspiration hazard No data available

---

### Section 12: Ecological Information

Toxicity to fish Semi-static test LC50 – *Leuciscus idus* (Golden Orfe) – 31.6 mg/l - 96.0 h

Toxicity to daphnia and other aquatic invertebrates Immobilisation EC50 – *Daphnia Magna* (Water Flea) – 4.6 mg/l – 48 h (OECD Test Guideline 202)

Toxicity to Algae Static test EC50 – *Desmodesmus Subspicatus* (Green Algae) 5 mg/l – 72 h

Toxicity to bacteria EC10 – *Pseudomonas Putida* – 96 mg/l – 18h

Persistence / Degradability Not available.

Mobility Not available.

Environmental Protection Do not allow product to enter drains, waterways or sewers.

Other adverse effects Acutely harmful to aquatic life

---

### Section 13: Disposal Considerations

# Safety Data Sheet

## H3410 PERFECT CAST DEEP HARDENER



ATL composites

Disposal Considerations Dispose of waste according to federal, EPA and state regulations. Do not allow product to enter drains, waterways or sewers.

---

### Section 14: Transport Information

ADG UN/ID No : UN2735  
Proper shipping name : AMINES, LIQUID, CORROSIVE, N.O.S  
Class : 8  
Packing Group : III  
Marine Pollutant : YES

IATA UN/ID No : UN2735  
Proper shipping name : AMINES, LIQUID, CORROSIVE, N.O.S  
Class : 8  
Packing Group : III  
Marine Pollutant : YES  
ERG : 8L

IMDG UN/ID No : UN2735  
Proper shipping name : AMINES, LIQUID, CORROSIVE, N.O.S  
Class : 8  
Packing Group : III  
Marine Pollutant : YES  
EmS : F-A,S-B

RID / ADR UN/ID No : UN2735  
Proper shipping name : AMINES, LIQUID, CORROSIVE, N.O.S  
Class : 8  
Packing Group : III  
EAC : 2X  
HIN : 80  
Marine Pollutant : YES

---

### Section 15: Regulatory Information

Regulatory Information Australia: Classified as hazardous according to criteria of National Occupational Health and Safety Commission (NOHSC).

Poisons Schedule Schedule 5

---

### Section 16: Other Information

Contact Person/Point PRODUCT INFORMATION MANAGER: (+61) 7 5563 1222  
12-14 Production Avenue, Ernest, Queensland, Australia

The information provided in this Safety Data Sheet is correct to the best of our knowledge, information and belief at the date of its publication. The information given is designed only as a guidance for safe handling, use, processing, storage, transportation, disposal and release and is not to be considered a warranty or quality specification. The information relates only to the specific material designated and may not be valid for such material used in combination with any other materials or in any process, unless specified in the text.

# Safety Data Sheet

## R3410 PERFECT CAST DEEP HARDENER

Version 1



ATL composites

### Section 1: Identification of the substance / mixture and of the supplier

Trade Name	R3410 PERFECT CAST DEEP HARDENER
Product Code	R3410
Recommended Use	Used in conjunction with epoxy curing agent for adhesive and composites applications
Company	ATL Composites
Address	12-14 Production Ave Ernest 4214
Telephone	+61 7 5563 1222 (Monday-Friday 8:30am-5:00pm)
Emergency Telephone Number	+61 7 5563 1222 (Monday-Friday 8:30am-5:00pm)
Revision Date	22 <sup>nd</sup> November 2018

### Section 2: Hazards Identification

GHS Classification: Skin Corrosion / Irritation (Category 2)  
Serious Eye Damage / Eye Irritation (Category 2)  
Skin Sensitisation (Category 1)  
Chronic Aquatic Toxicity (Category 2)

Non Dangerous Goods for transport according to ADG-7 (Special Provision AU01)

### GHS Label elements, including precautionary statements

Pictogram



Signal word Warning

Hazard statement(s)

H315	Causes skin irritation.
H317	May cause allergic skin irritation.
H318	Causes serious eye irritation.
H411	Toxic to aquatic life with long lasting effects.

Precautionary statement(s)

P261	Avoid breathing dust / fumes / gas / mist / vapours / spray/
P264	Wash skin thoroughly after handling.
P272	Contaminated work clothing should not be allowed out of the workplace.
P280	Wear protective gloves / eye protection / face protection.
P273	Avoid release into the environment.



# Safety Data Sheet

## R3410 PERFECT CAST DEEP HARDENER

Version 1



ATL composites

### Response

P302 + P352  
P305 + P351 + P338  
IF ON SKIN: Wash with plenty of soap and water.  
IF IN EYES: Rinse cautiously with water for several minutes.  
Remove contact lenses, if present and easy to do. Continue rinsing.

P310  
P321  
Immediately call a POISON CENTER or doctor / physician.  
Specific treatment (see supplement first aid instructions on this label).

P333 + P313  
P362  
If skin irritation or rash occurs: Get medical advice / attention.  
Take off contaminated clothing and wash before reuse.

### Disposal

P501  
Dispose of contents / container to an approved waste disposal plant

### Section 3: Composition / Information on Ingredients

Component	Classification	Concentration
4,4'-Isopropylidenediphenol-epichlorohydrin copolymer Common Name: Bisphenol A diglycidyl ether polymer	25085-99-8	>60
Phenol-formaldehyde polymer glycidyl ether Common name: Bisphenol F diglycidyl ether polymer	28064-14-4	10 - 30
1,6-hexanediglycidyl ether	16096-31-4	10 - 30
Aliphatic glycidylether of C <sub>12</sub> - C <sub>14</sub> alcohols	68609-97-2	10 - 30
Other ingredients determined not to be hazardous	-	To 100

### Section 4: First Aid Measures

General Advice  
Seek medical advice. If breathing has stopped or is laboured give assisted respirations. Supplemental oxygen may be indicated. If the heart has stopped begin cardiopulmonary resuscitation immediately.

Inhalation  
Remove the source of contamination or move the victim to fresh air. Ensure airways are clear and have qualified person give oxygen through a face mask if breathing is difficult. If symptoms develop and persist seek medical attention.

# Safety Data Sheet

## R3410 PERFECT CAST DEEP HARDENER

Version 1



ATL composites

Ingestion	DO NOT INDUCE VOMITING. Immediately wash out mouth with water. In general no treatment is necessary unless large quantities are ingested, however, seek medical attention.
Skin	Remove material from skin immediately by washing with soap and plenty of water. Remove contaminated clothing and shoes while washing. Seek medical attention if irritation persists. Wash clothing before reuse. Discard items which cannot be decontaminated, including leather articles such as shoes, belts and watchbands.
Eye	If contact with the eye(s) occurs, wash with copious amounts of water holding eyelid(s) open remove contact lenses after the initial 1-2 minutes and continue flushing for several additional minutes. Take care not to rinse contaminated water unto the non-affected eye. If symptoms persist seek medical attention, preferably an ophthalmologist. Suitable emergency eye wash facilities should be available in the work area.
First Aid Facilities	Eye wash and normal wash room facilities.
Advice to Doctor	Treat symptomatically
Other Information	For advice, contact a Poisons Information Center (Phone e.g Australia 131 126)

---

### Section 5: Fire Fighting Measures

Suitable extinguishing media	Water fog or fine spray. Dry chemical fire extinguishers. Carbon dioxide fire extinguishers. Foam. Alcohol resistant foams (ATC type) are preferred. General purpose synthetic foams (including AFFF) or protein foams may functions, but will be less effective. Water fog, applied gently may be used as a blanket for fire extinguishment.
Hazards from Combustion Products	During a fire, smoke may contain the original material in addition to combustion products of varying composition which may be toxic and/or irritating. Combustion products may include and are not limited to: Phenolics, Carbon Monoxide, Carbon Dioxide.
Precautions in connection with Fire	Keep people away. Isolate fire and deny unnecessary entry. Use water spray to cool fire exposed containers and fire affected zone until fire is out and danger of reignition has passed. Fight fire from protected location or safe distance. Consider the use of unmanned hose holders or monitor nozzles. Immediately withdraw all personnel from the area in cases of rising sound from venting safety device or discolouration of the container. Do not use direct water stream. May spread fire. Move container from fire if this is possible without hazard. Burning liquids may be moved by flushing with water to protect personnel and minimize property damage. Water fog, applied gently may be used as a blanket for fire extinguishment. Contain fire water run-off if possible. Fire water run-off, if not contained, may cause environmental damage.

---

### Section 6: Accidental Release Measures

# Safety Data Sheet

## R3410 PERFECT CAST DEEP HARDENER

Version 1



ATL composites

Environmental precautions	Wear appropriate personal protective equipment and clothing to minimise exposure. Dike and contain the spill. Prevent the material from entering into drains, ditches or other water ways. Place inert absorbent material onto spillage. Do not dilute material but contain. Dispose of waste according to federal, Environmental Protection Authority and state regulations.
Clean-up methods – small spillage	Soak up with an absorbent such as clay, sand or other suitable material. Place in non-leaking container. Seal tightly for proper disposal.
Clean-up methods – large spillage	Remove with vacuum trucks or pump to storage/salvage vessels. Soak up residue with an absorbent such as clay, sand or other suitable material; place in non-leaking containers for proper disposal.

---

### Section 7: Handling and Storage

#### Storage

Precautions for Safe Handling Avoid prolonged or repeated contact with skin, eyes and clothing. Avoid contact with skin, eyes and clothing wash thoroughly after handling. **WARNING.** May cause skin and eye irritation. May cause skin sensitization. Containers, even those that have been emptied, can contain hazardous product residues. Wash with soap and water before eating, drinking, smoking, applying cosmetics, or using toilet facilities. Launder contaminated clothing before reuse. Contaminated leather articles, including shoes cannot be decontaminated and should be destroyed to prevent reuse.

Conditions for Safe Storage Store in a cool, dry, well-ventilated area out of direct sunlight. Keep containers closed when not in use.

---

### Section 8: Exposure Controls / Personal Protection

National Exposure Standards No exposure standards have been established for this material by the Australian National Occupational Health and Safety Commission (NOHSC) or the Occupational Safety and Health Service (OHS) of the New Zealand Department of Labour. However, exposure standards for ingredients are stated below:

Australian National Occupational Health and Safety Commission (NOHSC) exposure standards:

Biological Limit Values No biological limit allocated.

Engineering Controls Provide sufficient ventilation to keep airborne levels below the exposure limit. Where vapours or mist are generated, particularly in enclosed areas, and natural ventilation is inadequate, a local exhaust ventilation system is required. Provide readily accessible eye wash stations and safety showers.

Respiratory Protection Where ventilation is inadequate the use of an Air Purifying Respirator with a replaceable organic vapour filter complying with AS/NZS 1715 and AS/NZS 1716 is recommended.

# Safety Data Sheet

## R3410 PERFECT CAST DEEP HARDENER

Version 1



ATL composites

Eye Protection	Safety glasses with side shields, goggles or full-face shield as appropriate recommended. Final choice of appropriate eye/face protection will vary according to individual circumstances i.e. methods of handling or engineering controls and according to risk assessments undertaken. Eye protection should conform with Australian/New Zealand Standard AS/NZS 1337 – Eye protectors for Industrial Applications.
Hand Protection	Wear gloves of impervious material such as impervious PVC or rubber gloves. Final choice of appropriate gloves will vary according to individual circumstances i.e. methods of handling or according to risk assessments undertaken. Reference should be made to AS/NZS 2161.1 Occupational protection gloves – Selection use and maintenance.
Body Protection	Suitable work wear should be worn to protect personal clothing. Industrial clothing should conform to the specifications detailed in AS/NZS 2919: Industrial Clothing.

---

### Section 9: Physical and Chemical Properties

Form	Liquid
Colour	Clear
Odour	Little
pH	Not Available
Melting Point	Not Determined
Flash Point	93°C Closed Cup
Boiling Point	320°C DSC Decomposition.
Vapour Density	Not Available
Vapour Pressure	<0.001 kPa @ 20°C
Density	1.10 to 1.13
Auto-Ignition Temperature	Not Available
Flammable Limits – Lower	Not Available
Flammable Limits – Upper	Not Available

---

### Section 10: Stability and Reactivity

Chemical Stability	Stable under normal conditions.
Conditions to Avoid	Extremes of temperature and direct sunlight. Can react vigorously with strong oxidizing agents, strong lewis or mineral acids and organic bases. Avoid contact with water or liquids. Do not allow molten product to contact water or other liquids.

# Safety Data Sheet

## R3410 PERFECT CAST DEEP HARDENER

Version 1



ATL composites

Reaction with some curing agents may produce considerable heat and possible violent decomposition.

Incompatible Materials Strong oxidising agents.

Hazardous Decomposition Products Carbon Monoxide

Hazardous Polymerisation Reacts violently with strong oxidising agents

---

### Section 11: Toxicological Information

Acute oral toxicity LD50 Low Toxicity Rat LD50 >15,000mg/kg

Acute dermal Toxicity LD50 Low Toxicity Rabbit LD50 >23,000mg/kg

Inhalation At room temperature, exposure to vapour is minimal due to low volatility. Vapour from heated material, mist or aerosols may cause respiratory irritation. The LC50 has not been determined.

Skin Irritating to skin. This product may cause sensitisation in some individuals.

Eyes Irritating to eyes. On eye contact this product will cause tearing, stinging, blurred vision and redness.

Specific Target Organ Systemic Toxicity (Single Exposure) Evaluation of available data suggests that this material is not an STOT-SE toxicant

Specific Target Organ Systemic Toxicity (Repeated Exposure) Except for skin sensitisation, repeated exposures to low molecular weight epoxy resins of this type are not anticipated to cause any significant adverse effects.

Carcinogenicity Many studies have been conducted to assess the potential carcinogenicity of diglycidyl ether of bisphenol A (DGEbPA). Indeed, the most recent review of the available data by the International Agency for Research on Cancer (IARC) has concluded that DGEbPA is not classified as a carcinogen. Although some weak evidence of carcinogenicity has been reported in animals, when all the data is considered, the weight of evidence does not show that DGEbPA is carcinogenic.

Teratogenicity Resins based on diglycidyl ether of bisphenol A (DGEbPA) did not cause birth defects or other adverse effects on the fetus when pregnant rabbits were exposed by skin contacts, the most likely route of exposure, or when pregnant rats or rabbits were exposed orally.

Reproductive Toxicity

# Safety Data Sheet

## R3410 PERFECT CAST DEEP HARDENER

Version 1



ATL composites

### Section 12: Ecological Information

Ecotoxicity	Material is moderately toxic to aquatic organisms on an acute basis (LC50 or EC50 between 1 and 10 mg/L in the most sensitive species tested). Acute LC50 in water flea <i>Daphnia magna</i> is 1.3 mg/L. Acute LC50 in fathead minnow ( <i>Pimephales promelas</i> ) is 3.1 mg/L. Toxicity to aquatic species occurs at concentrations greater than water solubility. Maximum acceptable toxicant concentration (MATC) in water flea <i>Daphnia magna</i> is 0.55 mg/L. Growth inhibition threshold in bacteria is >42.6 mg C/L. Inhibitory concentration (IC50) in OECD Activated Sludge Respiration Inhibition Test (OECD Test No. 209) is >100 mg/L.
Persistence / Degradability	Theoretical oxygen demand (ThOD) is calculated to be 2.35 p/p. In the atmospheric environment, material is estimated to have a tropospheric half-life of 1.92 hr. Biodegradation reached in Modified Zahn-Wellens/EMPA Test. (OECD Test No. 302B) after 28 days: 12%. The 20-Day Biochemical Oxygen Demand (BOD20) is <2.5%.
Movement and Partitioning	Bioconcentration potential is moderate (BCF between 100 and 3000 or Log Pow between 3 and 5). Measured log octanol/water partition coefficient (log Pow) is 3.7-3.9. Potential for mobility in soil is low (Koc between 500 and 2000). Soil organic carbon/water partition coefficient (Koc) is estimated to be 1800-4400. Henry's Law Constant (H) is estimated to be <6.94E-09 atm-m <sup>3</sup> /mole. Log octanol/water partition coefficient (log Pow) is estimated, using a structural fragment method, to be 3.84.
Environmental Protection	Do not allow product to enter drains, waterways or sewers.

### Section 13: Disposal Considerations

Disposal Considerations	DO NOT DUMP INTO ANY SEWERS, ON THE GROUND, OR INTO ANY BODY OF WATER. Dispose of waste according to federal, EPA and state regulations.
-------------------------	---

### Section 14: Transport Information

ADG	Not subject to the ADG Code when transported by Road or Rail. (ADG 7, Special Provision AU01)
IATA	Proper shipping name: Environmentally hazardous substance, liquid, N.O.S (EPOXY RESIN) Class : 9 UN/ID No : UN3082 Packing Group : III ERG : 9L
IMDG	Proper shipping name: Environmentally hazardous substance, liquid, N.O.S (EPOXY RESIN) Class : 9 UN/ID No : UN3082 Packing Group : III EmS : F-A, S-F
RID / ADR	Proper shipping name: Environmentally hazardous substance, liquid,

# Safety Data Sheet

## R3410 PERFECT CAST DEEP HARDENER

Version 1



ATL composites

N.O.S (EPOXY RESIN)  
Class : 9  
UN/ID No : UN3082  
Packing Group : III  
EAC : •3Z  
HIN : 90

---

### Section 15: Regulatory Information

Regulatory Information Australia: Classified as hazardous according to criteria of National Occupational Health and Safety Commission (NOHSC).

Poisons Schedule 5S

National and or International Regulatory Information New Zealand: Classified as Hazardous according to the Hazardous substances (Classification) Regulations 2001.

Hazard Category Irritant. Sensitiser.

---

### Section 16: Other Information

#### Contact

#### Person/Point

PRODUCT INFORMATION MANAGER: (+61) 7 5563 1222  
12-14 Production Av Ernest Queensland, Australia

The information provided in this Safety Data Sheet is correct to the best of our knowledge, information and belief at the date of its publication. The information given is designed only as a guidance for safe handling, use, processing, storage, transportation, disposal and release and is not to be considered a warranty or quality specification. The information relates only to the specific material designated and may not be valid for such material used in combination with any other materials or in any process, unless specified in the text.